Informational Public Workshop:

Malibu Creek & Lagoon


TMDL & Process & Next Steps




Dr. Cindy Lin, US EPA Region 9

May 1, 2013

Clean Water Act – "Fishable & Swimmable"













Protection of 23 Beneficial Uses in the Watershed:

Recreation, Wildlife, Freshwater Habitat, Estuarine Habitat; Spawning, Reproduction, Early Development of Aquatic Species, Rare,

Threatened, Endangered Habitat


Malibu Creek







Malibu Creek Algae coverage



What are Benthic Macroinvertebrates?



Nymph Mayfly




Adult Mayfly

WATER CANARIES: BENTHIC MACROINVERTEBRATES

Indicators of Water Quality & Ecosystem/Stream Health

- -Critical to balancing Ecosystem Process (energy flow in food webs)
- -Process leaf litter, dead organic material to prey for larger consumers

Important to nutrient cycling, aeration of sediment



Food Web and Ecosystem Cycling

Data Collection & Assessment


- Water Quality; Benthic Macroinvertebrates; Physical Habitat; Sediment Inventory (<u>Multiple Lines of Evidence</u>)
- Approximately 120 separate sets of data, reports, studies, covering 1998-2011
- Monterey/Modelo Formation; Wildfire History; Land Use History & Change;
- Incorporates Statewide approaches towards Biological Objectives and Nutrient Numeric Methods
- Reports & Studies from local and state scientific experts, NPS, CA DFG, SCCWRP, LVMWD, LA County, UCLA, US Santa Barbara, etc.

Causes/Stressors Evaluated

- Sedimentation
- Nutrient enrichment
- Reduced DO
- Toxicity
- Altered hydrology
- Channel alteration
- Fire regime
- Point source discharge

- Urban runoff
- Agricultural runoff
- Naturally elevated levels of phosphate, sulfate, TDS
- Invasive species (New Zealand mudsnails)

Potential Causes of Impaired Biological Condition




Process Continues

Implementation



Pace



Increasing Nitrogenleads to higher to Mat Algae Cover

Focusing on the growing season between June and September